


## Connecteurs à perforation d'isolant

### Insulating piercing connectors

Conectores a perforación simultánea

Conectores a perfuração do isolante

| Ref. | S (mm <sup>2</sup> )       |                         |
|------|----------------------------|-------------------------|
|      | S1                         | S2                      |
| P21  | 10-25 mm <sup>2</sup>      | 2,5-35 mm <sup>2</sup>  |
| P71  | 35-70 (95) mm <sup>2</sup> | 4-50 mm <sup>2</sup>    |
| P72  | 35-70 (95) mm <sup>2</sup> | 2x 6-50 mm <sup>2</sup> |
| P151 | 16-150 mm <sup>2</sup>     | 6-95 mm <sup>2</sup>    |
| P152 | 16-150 mm <sup>2</sup>     | 2x 6-50 mm <sup>2</sup> |



## Instalación · Installation · Mise en oeuvre · Instalação

